


# PERFORMA FOR THE SAFETY OF THE SCHOOL BUILDING

## PART-1

(To be filled by the Head of school/Instruction)

1. Name of the School — Jalandhar Public School.
2. Location — Jaitewali Road, Patara, Jalandhar.
3. Plot Area — 87,392 Sq. Ft.
4. Plinth Area — 60,000 Sq. Ft.
5. No. of Storey — 02 (Two)
6. Year of construction of the building
7. If the building has been constructed under the supervision of the qualified engineer, the following details may be given  
Name of the engineer — Mr. Rahul S/o Mr. Ramesh.  
a) Address of the engineer — T52, Bhargo Camp, Jalandhar.  
b) Set of structural drawing used in construction, if available  
c) Name and address of the architect — M/s Rajinder Associates, Sahota Complex, Jalandhar.
8. Whether the building has been constructed for the purpose  
a) School  Yes/No  
b) Residential purpose & converted for use as a school  Yes/No
9. Material used for roofs  
a) R.C.C. slabs  Yes/No  
b) R.S. joists and batons  Yes/No  
c) Wooden joists and battens  Yes/No
10. Material used for walls  
a) Mud mort  Yes/No  
b) Cement mortar  Yes/No  
c) Plaster i) Lime Mortar  Yes/No  
ii) Cement Mortar  Yes/No
11. Flooring  
a) Conglomerate  Yes/No  
b) Terrazo  Yes/No  
c) Brick Facing  Yes/No
12. A detail drawing indicating dimensions of the rooms along with size and location of doors and windows (attached)

  
Principal  
Jalandhar Public School  
Signature with stamp of  
The Head of the school

PART-II

(To be filled by the S.D.O. of P.W.D, B & R Department)

Jalandhar Public School, Jaittewah Road Patara Jalandhar

a) I have visited the above mentioned school on 30.3.2024 and have visually inspection it from all angle of safety and I find it fit from normal use as a school buildings.

b) In case any addition/alteration or expansion and modification of this building is to be carried out the same be carried out under the supervision of technically qualified Engineer and this Certificate may again be obtained after the completion from the undersigned.

c) In case the building is affected by flood, or there is settlement of walls/foundation or sagging of roofs etc. Immediate inspection of the undersigned be arranged to check the stability and safety of the Building.

d) This building can safely occupied for normal use upto (Indicate) year upto which it can be used for up to 31.3.2025 (2024-2025). The

~~School Building is VISIBLY SAFE & can be used upto 31.3.2025 (2024-2025).~~

Ref No

Spl 033

Dated

2/4/2024

[Signature]  
Sub Divisional Engineer  
Provincial Sub Divn. No.1  
PWD B&R Br. Jalandhar Cantt